



# KOMPSAT Imagery Quality Report

- KOMPSAT-2, 3, 3A (February ~ March 2020) -

□ Quality of KOMPSAT-2, 3, 3A


Satellite	Location(Geometric)	MTF(Spatial)
 KOMPSAT-3	28.4m RMSE	10.0%
 KOMPSAT-3A	6.7m RMSE	9.6%

※ Above location (geometric) accuracy is a result processed with POD/PAD.


※ Above MTF values are measured with MTFC off.



### KOMPSAT-3 Location Accuracy




### KOMPSAT-3A Location Accuracy






### KOMPSAT-2 MTF



※ No valid scenes were acquired on January to March 2020.



### KOMPSAT-3 MTF





## KOMPSAT-3A MTF

